

ALASKA DEPARTMENT OF ENVIRONMENTAL CONSERVATION OIL & HAZARDOUS SUBSTANCES SPILL NOTIFICATION

ADEC SPILL #	ADEC FILE	#		ADEC LC	ADEC LC				
PERSON REPORTING	PHONE NUM	MBER		REPORTED HOW? Troopers phone fax					
DATE/ TIME OF SPILL	DATE/	TIME DISCO	OVEREI	D	DATE/TIME R	EPORTED			
LOCATION/ADDRESS		LAT.			SUBSTANCE T A) CR EHS HS N	NC PW UNK	PRODUCT A)		
		LONG.			B) CR EHS HS N	IC PW UNK	B)		
	ANTITY CONTA			QUANTITY RECOV		QUANTITY	Y DISPOSED		
□ gallons		☐ gallon ☐ pound			□ gallons □ pounds			□ gallons □ pounds	
POTENTIAL RESPONSIBLE PARTY C-Pla	an Holder? YES □	1		FACILITY TYPE	□ pounds			pounds	
SOURCE OF SPILL		_	_		_	_	□ >400 G	Γ Vessel?	
CAUSE OF SPILL (List Primary Cause first)							☐ Acciden ☐ Human ☐ Structur ☐ Other		
CLEANUP ACTIONS							L Ome		
DISPOSAL METHODS AND LOCATION									
RESOURCES AFFECTED/THREATENED (Water sources, wildlife, wells. etc.)				AIR LAND MARI	NE FRESH SU	RF. AREA A	FFECTED	SURF. TYPE	
COMMENTS				_					
		DEC	USE	ONLY					
SPILL NAME, IF ANY				S OF DEC STAFF RE	C-PLAN MGR NOTIFIED YES □ NO □				
DEC RESPONSE ☐ phone follow-up ☐ field visit ☐ took report	☐ First and		Open/No			Monitoring	TION Transferred	to CS or STP	
STATUS OF CASE (circle)	OPEN C	CLOSED		DATE (CASE CLOS	ED			
COMMENTS:									
REPORT PREPARED BY				1	DATE				



ALASKA DEPARTMENT OF ENVIRONMENTAL CONSERVATION OIL & HAZARDOUS SUBSTANCES SPILL NOTIFICATION

ADEC SPILL#		ADEC FILE #					ADEC LO	ADEC LC				
PERSON REPORTING Bob Cleveland		PHONE NUMBER 235-7556					REPORTED HOW? Troopers phone fax					
				FIME DISCOVERED 5/05 0900				DATE/TIME REPORTED 4/15/05 1015				
LOCATION/ADDRESS Perl Rock, south side of Perl Island			LAT.		59 06'N 151 41'W QUANTITY RECOVED 0		SUBSTANCE T A) CR EHS HS N B) CR EHS HS N	C PW UNK	A)	PRODUCT A) North Slope Crude Oil B) Y DISPOSED gallons		
Kennedy Entrance Cook Inleguantity Spilled	et QUANTITY 0	CONTA	CONTAINED				<u> </u>					
380,000 DDIS pounds	C-Plan Holder?	? YES ☑	□ poun		FACILITY TYPE		□ pounds	<u> </u>	D pounds			
Tesoro Alaska Company TAPS trade vessel												
SOURCE OF SPILL T/V Cook Inlet										>400 (GT Vessel?	
CAUSE OF SPILL (List Primary Cause first) Power loss caused vessel to drift into Perl Rock and break apart on the rocks Accident Human Factors Structural/Mechanical Other												
CLEANUP ACTIONS None				4								
DISPOSAL METHODS AND LOCATION n/a												
RESOURCES AFFECTED/THREATENED wildlife, commercial and sport fishing, subsistence Water sources, wildlife, wells. etc.) AIR LAND MARINE FRESH 20 square miles Water COMMENTS												
Response actions already taken are: Command Post and ICS establishment; overflight; assessment of quantity spilled												
			DEC	USE	EONLY							
SPILL NAME, IF ANY T/V Cook Inle	NAME, IF ANY T/V Cook Inlet			NAMI	IES OF DEC STAFF RESPONDING			C-PLAN MGR NOTIFIED YES □ NO □				
DEC RESPONSE □ phone follow-up □ field visit □ took re	eport	☐ First and		Open/N		ed		Ionitoring	□ Tr		ed to CS or STP	
STATUS OF CASE (circle) COMMENTS:	OPEN	N C	CLOSED		DATE	E CA	ASE CLOS	ED				
REPORT PREPARED BY						DA	ТЕ					

Additional Instructions Page: ADEC Spill Notification

By clicking on the i, you've reached this instructional page. Here you can find special instructions on individual text fields.

Page 1:

ADEC Spill #-- This number will be assigned by ADEC for internal reference.

ADEC File #-- This number will be assigned by ADEC for internal reference.

ADEC LC—This number will be assigned by ADEC for internal reference.

SURF. TYPE—This is the oil receiving medium

More Information on this Form

When do you need this form?

After an oil spill has been identified.

Who fills out this form?

A representative with the responsible party.

Who signs this form?

No signature is required.

Where does this form get delivered?

To the ADEC office at: 555 Cordova St. Anchorage, AK 99501.